

Figure 1






Figure 2A


[illegible]

Figure 2B




Figure 26




Figure 20

0	A
1	A
2	A
3	B
4	C
5	D
6	D
7	E
8	E
9	X
10	X
11	X
12	X
13	X
14	X
15	X

300

7.4.R

0	A
1	A
2	A
3	B
4	C
5	D
6	D
7	R
8	R
9	R
10	R
11	X
12	X
13	X
14	X
15	X

300

10.4.Z

0	A
1	A
2	A
3	B
4	C
5	D
6	D
7	R
8	R
9	R
10	Z
11	Z
12	Z
13	Z
14	X
15	X

310

2.6.Y

0	A
1	A
2	Y
3	Y
4	Y
5	Y
6	Y
7	Y
8	R
9	R
10	Z
11	Z
12	Z
13	Z
14	X
15	X

314

Figure 3A

0	A
1	A
2	A
3	B
4	C
5	D
6	D
7	E
8	E
9	X
10	X
11	X
12	X
13	X
14	X
15	X

300

0	A
1	A
2	A
3	B
4	C
5	D
6	D
7	E
8	E
9	X
10	Z
11	Z
12	Z
13	Z
14	X
15	X

10:14:2

0	A
1	A
2	Y
3	Y
4	Y
5	Y
6	Y
7	Y
8	E
9	X
10	Z
11	Z
12	Z
13	Z
14	X
15	X

2:6:Y

0	A
1	A
2	Y
3	Y
4	Y
5	Y
6	Y
7	R
8	R
9	R
10	R
11	Z
12	Z
13	Z
14	X
15	X

7:4:R

316

Figure 3B

1050T-258T-100T





Figure 4






Figure 6




Figure 7




Figure 2




Figure 9













Figure 10A



108



2012







Figure 100






Figure 10E




Figure 10F







Figure 106




Figure 10H